


Fig. 1






Fig. 3A




Fig. 3B




Fig. 48






Fig. 5



Fi g. 6



E. g.








Fig. 8









Fi g . 10




Fi g. 10B








Fi g. 12∆



Fi g. **12**B







layout diagram of merchenical arms sensors (47 points)

Fig. Ib




Fig. 16







Fig. 17




Fi g. 18





el ectri cal consumpti on val I ey



Fi g. 21








Fig. 22






Fi g. 24∆





Fi g<sub>.</sub> 25∆



**Fi g**. **25**₿






Fig 26∆



**Fig. 26**B



Fi g. 27

